

Shari Bradix,

Yes, I had to replace the ground rod connector as a result of work being done on the sidewalk. The connector was submerged in cement, un-attached from the ground rod. See the following photos:

