

Larry,

Attached is the engineers reports. Please provide the location of the A/C unit that was removed from the subject premises. We need to determine year make and model of the unit.

Once you have reviewed the reports, let's discuss resolution of the claim.

Thank you

Shari L. Bradix, CRIS  
Managing Claims Consultant  
CNA Construction Defect Claims  
P.O. Box 8317  
Chicago, IL 60680-8317  
Tel. (415) 932-7213  
Fax:(866) 622-7517  
Toll: (800) 262-7161

This e-mail message, including any attachments and appended messages, is for the sole use of the intended recipients and may contain confidential and legally privileged information. If you are not the intended recipient, any review, dissemination, distribution, copying, storage or other use of all or any portion of this message is strictly prohibited. If you received this message in error, please immediately notify the sender by reply e-mail and delete this message in its entirety.